

序号	报告编号	发布日期	结论	影像资料
32	GX-B1340/21-9-22023	6.10	依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。	
33	GX-B1340/21-9-22024	6.10	依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。	
34	GX-B1340/21-9-22025	6.10	依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。	
35	GX-B1340/21-9-22026	6.10	依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。	
36	GX-B1340/21-9-22037	6.10	依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。	

37	GX-B1340/21-9-22038	6.10	依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。	
38	GX-B1341/21-9-22026	2022.6.27	合格	
39	GX-B1341/21-9-22027	2022.6.27	合格	
40	GX-B1341/21-9-22028	2022.6.27	合格	
41	GX-B1341/21-9-22029	2022.6.27	合格	
42	GX-B1341/21-9-22030	2022.6.27	合格	
43	GX-B1341/21-9-22031	2022.6.27	合格	
44	GX-B1341/21-9-22032	2022.6.27	合格	
45	GX-B1341/21-9-22033	2022.6.27	合格	
46	GX-B1341/21-9-22034	2022.6.27	合格	
47	GX-B1341/21-9-22035	2022.6.27	合格	

48	GX-B1341/21-9-22036	2022. 6. 27	合格	
49	GX-B1341/21-9-22037	2022. 6. 27	合格	
50	GX-B1341/21-9-22038	2022. 6. 27	合格	
51	GX-B1341/21-9-22039	2022. 6. 27	合格	
52	GX-B1341/21-9-22040	2022. 6. 27	合格	
53	GX-B1341/21-9-22041	2022. 6. 27	合格	
54	GX-B1341/21-9-22042	2022. 6. 27	合格	
55	GX-B1341/21-9-22043	2022. 6. 27	合格	
56	GX-B1341/21-9-22044	2022. 6. 27	合格	
57	GX-B1341/21-9-22045	2022. 6. 27	合格	
58	GX-B1341/21-9-22046	2022. 6. 27	合格	
59	GX-B1341/21-9-22047	2022. 6. 27	合格	

60	GX-B1341/21-9-22048	2022. 6. 27	合格	
61	GX-B1341/21-9-22049	2022. 6. 27	合格	
62	GX-B1341/21-9-22050	2022. 6. 27	合格	
63	GX-B1341/21-9-22051	2022. 6. 27	合格	
64	GX-B1341/21-9-22052	2022. 6. 27	合格	
65	GX-B1341/21-9-22053	2022. 6. 27	合格	
66	GX-B1341/21-9-22077	6. 20	综合判定：合格	

67	GX-B1343/21-9-22013	6.20	无	 <p>2022.06.12</p>
68	GX-B1343/21-9-22014	6.22	无	 <p>王井</p> <p>高高兴兴上班</p> <p>平平安安回家</p> <p>2022.06.11</p>

69	GX-B1341/21-9-22018	6.22	综合判定：合格。	 <p>2022.05.09</p>
70	GX-B1341/21-9-22019	6.22	综合判定：合格。	 <p>2022.05.09</p>

71	GX-B1341/21-9-22020	6.22	综合判定：合格。	
72	GX-B1341/21-9-22021	6.22	综合判定：合格。	

73	GX-B1341/21-9-22022	6.22	综合判定：合格。	
74	GX-B1341/21-9-22023	6.22	综合判定：合格。	

75	GX-B1343/21-9-22009	6.22	/	 <p>2022.05.09</p>
76	GX-B1343/21-9-22010	6.22	/	 <p>2022.05.10</p>

77	GX-B1347/21-9-22005	6.22	/	 <p>2022.05.09</p>
78	GX-B1347/21-9-22006	6.22	/	 <p>2022.05.10</p>

79	GX-B1341/21-9-22076	6.23	综合判定：合格。	 <p>2022.5.30</p>
80	GX-B1343/21-9-22012	6.22	/	 <p>2022.5.30</p>

81	GX-B1347/21-9-22009	6.22	/	
82	GX-B1340/21-9-22045	6.28	<p>依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。</p>	

83	GX-B1340/21-9-22046	6.28	<p>依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。</p>	
84	GX-B1341/21-9-22072	6.28	<p>综合判定：合格。</p>	

85	GX-B1341/21-9-22073	6.28	综合判定：合格。	
86	GX-B1341/21-9-22074	6.28	综合判定：合格。	

87	GX-B1341/21-9-22075	6.28	综合判定：合格。	 <p>2022.05.26</p>
88	GX-B1341/21-9-22079	6.28	综合判定：合格。	 <p>2022.06.14</p>

89	GX-B1341/21-9-22025	2022. 6. 27	合格	 <p>2022.05.12</p>
90	GX-B1343/21-9-22015	2022. 6. 17	见报告	 <p>2022.06.12</p>

91	GX-B1341/21-9-22026	2022. 6. 27	合格	
----	---------------------	-------------	----	--

92	GX-B1341/21-9-22027	2022. 6. 27	合格	 <p>2022.05.17</p>
93	GX-B1341/21-9-22028	2022. 6. 27	合格	 <p>2022.05.17</p>

94	GX-B1341/21-9-22029	2022. 6. 27	合格	
95	GX-B1341/21-9-22030	2022. 6. 27	合格	

96	GX-B1341/21-9-22031	2022. 6. 27	合格	
97	GX-B1341/21-9-22032	2022. 6. 27	合格	

98	GX-B1341/21-9-22033	2022. 6. 27	合格	
99	GX-B1341/21-9-22034	2022. 6. 27	合格	

100	GX-B1341/21-9-22035	2022. 6. 27	合格	
101	GX-B1341/21-9-22036	2022. 6. 27	合格	

102	GX-B1341/21-9-22037	2022. 6. 27	合格	
103	GX-B1341/21-9-22038	2022. 6. 27	合格	

104	GX-B1341/21-9-22039	2022. 6. 27	合格	 <p>2022.05.18</p>
105	GX-B1341/21-9-22040	2022. 6. 27	合格	 <p>2022.05.19</p>

106	GX-B1341/21-9-22041	2022. 6. 27	合格	 <p>2022.05.19</p>
107	GX-B1341/21-9-22042	2022. 6. 27	合格	 <p>2022.05.19</p>

108	GX-B1341/21-9-22043	2022. 6. 27	合格	 <p>2022.05.19</p>
109	GX-B1341/21-9-22044	2022. 6. 27	合格	 <p>2022.05.19</p>

110	GX-B1341/21-9-22045	2022. 6. 27	合格	
111	GX-B1341/21-9-22046	2022. 6. 27	合格	

112	GX-B1341/21-9-22047	2022. 6. 27	合格	 <p>2022.05.19</p>
113	GX-B1341/21-9-22048	2022. 6. 27	合格	 <p>2022.05.19</p>

114	GX-B1341/21-9-22049	2022. 6. 27	合格	
115	GX-B1341/21-9-22050	2022. 6. 27	合格	

116	GX-B1341/21-9-22051	2022. 6. 27	合格	
117	GX-B1341/21-9-22052	2022. 6. 27	合格	

118	GX-B1341/21-9-22026	2022. 6. 27	合格	
119	GX-B1341/21-9-22027	2022. 6. 27	合格	

120	GX-B1341/21-9-22028	2022. 6. 27	合格	
121	GX-B1341/21-9-22029	2022. 6. 27	合格	

122	GX-B1341/21-9-22030	2022. 6. 27	合格	
123	GX-B1341/21-9-22031	2022. 6. 27	合格	

124	GX-B1341/21-9-22032	2022. 6. 27	合格	
125	GX-B1341/21-9-22033	2022. 6. 27	合格	

126	GX-B1341/21-9-22034	2022. 6. 27	合格	
127	GX-B1341/21-9-22035	2022. 6. 27	合格	

128	GX-B1341/21-9-22036	2022. 6. 27	合格	
129	GX-B1341/21-9-22037	2022. 6. 27	合格	

130	GX-B1341/21-9-22038	2022. 6. 27	合格	 <p>2022.05.18</p>
131	GX-B1341/21-9-22039	2022. 6. 27	合格	 <p>2022.05.18</p>

132	GX-B1341/21-9-22040	2022. 6. 27	合格	
133	GX-B1341/21-9-22041	2022. 6. 27	合格	

134	GX-B1341/21-9-22042	2022. 6. 27	合格	 <p>2022.05.19</p>
135	GX-B1341/21-9-22043	2022. 6. 27	合格	 <p>2022.05.19</p>

136	GX-B1341/21-9-22044	2022. 6. 27	合格	
137	GX-B1341/21-9-22045	2022. 6. 27	合格	

138	GX-B1341/21-9-22046	2022. 6. 27	合格	 <p>2022.05.19</p>
139	GX-B1341/21-9-22047	2022. 6. 27	合格	 <p>2022.05.19</p>

140	GX-B1341/21-9-22048	2022. 6. 27	合格	
141	GX-B1341/21-9-22049	2022. 6. 27	合格	

142	GX-B1341/21-9-22050	2022. 6. 27	合格	
143	GX-B1341/21-9-22051	2022. 6. 27	合格	

144	GX-B1341/21-9-22052	2022. 6. 27	合格	
145	GX-B1341/21-9-22083	2022. 6. 30	合格	

146	GX-B1343/21-9-22021	2022. 6. 30	/	
147	GX-B1343/21-9-22022	2022. 6. 30	/	
148	GX-B1343/21-9-22015	2022. 6. 17	/	

149	GX-B1341/21-9-22084	2022. 6. 30	合格	 A nighttime photograph showing two workers in red protective suits and hard hats. They are standing in front of a dark structure with a white grid pattern, possibly a tunnel entrance or a large pipe. One worker is holding a bright flashlight, illuminating the scene. The date '2022.6.21' is visible in the bottom right corner of the photo.
150	GX-B1343/21-9-22023	2022. 6. 30	/	 A daytime photograph of a tunnel entrance. Two workers in red protective suits are standing on either side of the entrance, holding a white safety tape across the opening. The tunnel is dark, and the surrounding area is brightly lit. There are signs on the wall, including one that says '安全第一 综合治理' (Safety First, Comprehensive Management). A white car is partially visible on the right side of the frame.

151	GX-B1370/21-9-22013	2022. 6. 22	除上述问题外，其余所检项目合格。	
152	GX-B1370/21-9-22014	2022. 6. 22	除上述问题外，其余所检项目合格。	