

序号	报告编号	发布日期	结论	影像资料
76	GX-B1310/21-2-22100	2022.7.6	合格	
77	GX-B1427/21-2-22100	2022.7.6	合格	

78	GX-B1310/21-2-22101	2022. 7. 6	合格	
79	GX-B1427/21-2-22101	2022. 7. 6	合格	
80	GX-B1310/21-2-22102	2022. 7. 6	合格	

81	GX-B1427/21-2-22102	2022. 7. 6	合格	
82	GX-B1328/20-2-22076	2022. 5. 24	合格	
83	GX-B1328/20-2-22077	2022. 5. 24	合格	

84	GX-B1329/21-2-22136~22139	2022. 6. 13	合格	
85	GX-B1303/21-2-22006	2022. 7. 6	合格	
86	GX-B1304/21-2-22014	2022. 7. 6	合格	

87	GX-B1304/21-2-22016	2022.7.6	合格	
88	GX-B1598/21-2-22085	2022.7.11	<p>实测钢丝绳有效截面积损失百分比最大为2.57%，小于5%为正常。</p>	
89	GX-B1598/21-2-22086	2022.7.11	<p>实测钢丝绳有效截面积损失百分比最大为0.36%，小于5%为正常。</p>	

90	GX-B1598/21-2-22087	2022. 7. 11	<p>实测钢丝绳有效截面积损失百分比最大为1.98%，小于5%为正常。</p>	
91	GX-B1598/21-2-22088	2022. 7. 11	<p>实测钢丝绳有效截面积损失百分比最大为1.11%，小于5%为正常。</p>	
92	GX-B1598/21-2-22089	2022. 7. 11	<p>实测钢丝绳有效截面积损失百分比最大为1.70%，小于5%</p>	

93	GX-B1598/21-2-22090	2022.7.11	实测钢丝绳有效截面积损失百分比最大为0.93%，小于5%为正常。 。	 <p>2022/06/28</p>
94	GX-B1598/21-2-22097	2022.7.11	实测钢丝绳有效截面积损失百分比最大为0.43%，小于5%为正常。 。	 <p>2022/06/30</p>

95	GX-B1598/21-2-22098	2022.7.11	实测钢丝绳有效截面积损失百分比最大为1.29%，小于5%为正常。 。	
96	GX-B1598/21-2-22099	2022.7.11	实测钢丝绳有效截面积损失百分比最大为1.12%，小于5%为正常。 。	

97	GX-B1598/21-2-22100	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为1.23%，小于5% 为正常。 。 +D2:D6	
98	GX-B1598/21-2-22101	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为2.58%，小于5% 为正常。 。	

99	GX-B1598/21-2-22102	2022. 7. 11	<p>实测钢丝绳有效截面积损失百分比最大为1.06%，小于5% 为正常。</p>	
100	GX-B1598/21-2-22103	2022. 7. 11	<p>实测钢丝绳有效截面积损失百分比最大为2.89%，小于5% 为正常。</p>	
101	GX-B1598/21-2-22104	2022. 7. 11	<p>实测钢丝绳有效截面积损失百分比最大为2.86%，小于5% 为正常。</p>	

102	GX-B1598/21-2-22105	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为2.89%，小于5% 为正常。 。	
103	GX-B1598/21-2-22106	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为2.18%，小于5% 为正常。 。	
104	GX-B1598/21-2-22107	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为0.28%，小于5% 为正常。 。	

105	GX-B1598/21-2-22108	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为1.18%，小于5% 为正常。 。	
106	GX-B1598/21-2-22041	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为3.71%，小于5% 为正常。 。	

107	GX-B1598/21-2-22042	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为3.08%，小于5% 为正常。 。	
108	GX-B1598/21-2-22043	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为3.57%，小于5% 为正常。 。	

109	GX-B1598/21-2-22044	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为4.51%，小于5% 为正常。 。	
110	GX-B1598/21-2-22045	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为2.66%，小于5% 为正常。 。	

111	GX-B1598/21-2-22046	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为1.72%，小于5% 为正常。 。	 <p>2022/05/24</p>
112	GX-B1598/21-2-22047	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为1.28%，小于5% 为正常。 。	 <p>2022/05/24</p>

113	GX-B1598/21-2-22048	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为2.65%，小于5% 为正常。 。	 <p>2022/06/24</p>
114	GX-B1598/21-2-22049	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为1.63%，小于5% 为正常。 。	 <p>2022/06/21</p>

115	GX-B1598/21-2-22050	2022. 7. 11	<p>实测钢丝绳有效截面积损失百分比最大为2.73%，小于5% 为正常。</p>	
116	GX-B1598/21-2-22051	2022. 7. 11	<p>实测钢丝绳有效截面积损失百分比最大为2.55%，小于5% 为正常。</p>	
117	GX-B1598/21-2-22052	2022. 7. 11	<p>实测钢丝绳有效截面积损失百分比最大为2.04%，小于5% 为正常。</p>	

118	GX-B1598/21-2-22053	2022. 7. 11	<p>实测钢丝绳有效截面积损失百分比最大为3.90%，小于5% 为正常。</p>	
119	GX-B1598/21-2-22054	2022. 7. 11	<p>实测钢丝绳有效截面积损失百分比最大为1.30%，小于5% 为正常。</p>	
120	GX-B1598/21-2-22055	2022. 7. 11	<p>实测钢丝绳有效截面积损失百分比最大为2.06%，小于5% 为正常。</p>	

121	GX-B1598/21-2-22056	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为2.98%，小于5% 为正常。 。	 <p>2022/07/11</p>
122	GX-B1598/21-2-22057	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为0.99%，小于5% 为正常。 。	 <p>2022/06/19</p>

123	GX-B1598/21-2-22058	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为1.73%，小于5% 为正常。 。	
124	GX-B1598/21-2-22059	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为1.65%，小于5% 为正常。 。	

125	GX-B1598/21-2-22060	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为2.47%，小于5% 为正常。 。	
126	GX-B1598/21-2-22061	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为2.05%，小于5% 为正常。 。	

127	GX-B1598/21-2-22062	2022.7.11	实测钢丝绳有效截面积损失百分比最大为3.48%，小于5% 为正常。 。	
128	GX-B1598/21-2-22063	2022.7.11	实测钢丝绳有效截面积损失百分比最大为2.51%，小于5% 为正常。 。	

129	GX-B1598/21-2-22064	2022. 7. 11	实测钢丝绳有效截面积损失百分比最大为3.03%，小于5% 为正常。 。	
-----	---------------------	-------------	--	---