

序号	报告编号	发布日期	结论	影像资料
895	GX-B1522/20-Y-23043	2023年4月11日	所检项目合格。	

896	GX-B1522/20-Y-23044	2023年4月11日	所检项目合格。	
897	GX-B1522/20-Y-23045	2023年4月11日	所检项目合格。	

898	GX-B1522/20-Y-23046	2023年4月11日	所检项目合格。	
-----	---------------------	------------	---------	---

899	GX-B1522/20-Y-23047	2023年4月11日	所检项目合格。	 A photograph showing a person wearing a high-visibility vest and a cap, seated inside a vehicle or machinery, operating a control panel. The interior has a glass roof structure. A yellow timestamp '2023/2/23' is visible in the bottom right corner of the photo.
-----	---------------------	------------	---------	--

900	GX-B1522/20-Y-23048	2023年4月11日	所检项目合格。	
-----	---------------------	------------	---------	---

901	GX-B1522/20-Y-23049	2023年4月11日	所检项目合格。	
-----	---------------------	------------	---------	---

902	GX-B1522/20-Y-23050	2023年4月11日	所检项目合格。	
-----	---------------------	------------	---------	---

903	GX-B1522/20-Y-23051	2023年4月11日	所检项目合格。	
-----	---------------------	------------	---------	---

904	GX-B1522/20-Y-23052	2023年4月11日	所检项目合格。	
-----	---------------------	------------	---------	---

905	GX-B1522/20-Y-23053	2023年4月11日	所检项目合格。	
-----	---------------------	------------	---------	---

906	GX-B1522/20-Y-23054	2023年4月11日	所检项目合格。	
907	GX-B1522/20-Y-23055	2023年4月11日	所检项目合格。	

908	GX-B1522/20-Y-23056	2023年4月11日	所检项目合格。	
-----	---------------------	------------	---------	---

909	GX-B1522/20-Y-23057	2023年4月11日	所检项目合格。	
-----	---------------------	------------	---------	---

910	GX-B1522/20-Y-23058	2023年4月11日	所检项目合格。	
911	GX-B1522/20-Y-23059	2023年4月11日	所检项目合格。	

912	GX-B1415/22-Y-23004	2023年4月12日	综合判定：合格。	
913	GX-B1310/21-Y-23059	2023年4月12日	符合标准要求。	

914	GX-B1310/21-Y-23060	2023年4月12日	符合标准要求。	 A photograph showing a worker in a red hard hat and purple jacket working on a blue industrial machine. The worker is using a tool to adjust or inspect a part of the machine. The background shows an industrial setting with various pipes and structures. A yellow timestamp '2023/3/18' is visible in the bottom right corner of the image.
915	GX-B1310/21-Y-23061	2023年4月12日	符合标准要求。	 A photograph showing a worker in a red hard hat and purple jacket working on a red industrial structure. The worker is using a tool to adjust or inspect a part of the structure. The background shows an industrial setting with various pipes and structures. A yellow timestamp '2023/3/18' is visible in the bottom right corner of the image.

916	GX-B1310/21-Y-23062	2023年4月12日	符合标准要求。	
917	GX-B1310/21-Y-23063	2023年4月12日	符合标准要求。	

918	GX-B1539/22-Y-23066	2023年4月12日	所检项目合格。	 A yellow LUDONG wheel loader is shown in an outdoor setting. Two workers, one in a blue uniform and one in a grey uniform, are standing in front of the machine. The loader has 'LUDONG' and 'M-6801' visible on its side. A yellow timestamp '2023/4/12' is in the bottom right corner of the photo.
919	GX-B1539/22-Y-23067	2023年4月12日	所检项目合格。	 A yellow LUDONG wheel loader is shown in an outdoor setting. Two workers, one in a grey uniform and one in a black uniform with a blue hard hat, are standing in front of the machine. The loader has 'LUDONG' and 'M-6802' visible on its side. A yellow timestamp '2023/4/12' is in the bottom right corner of the photo.

920	GX-B1539/22-Y-23068	2023年4月12日	所检项目合格。	
921	GX-B1539/22-Y-23069	2023年4月12日	所检项目合格。	

922	GX-B1539/22-Y-23070	2023年4月12日	所检项目合格。	
923	GX-B1539/22-Y-23071	2023年4月12日	所检项目合格。	

924	GX-B1415/22-Y-23005	2023年4月12日	综合判定：合格。	
925	GX-B1415/22-Y-23006	2023年4月12日	综合判定：合格。	

926	GX-B1417/22-Y-23042	2023年4月12日	综合判定：合格	 <p>A photograph showing two men standing in an open, paved area under a clear blue sky. The man on the left is wearing a blue hard hat, a blue jacket, and a high-visibility yellow safety vest. The man on the right is wearing a grey jacket and a blue hard hat. They are standing next to a dark-colored car. A date stamp '2023/4/8' is visible in the bottom left corner of the photo.</p>
927	GX-B1417/22-Y-23043	2023年4月12日	综合判定：合格	 <p>A photograph showing two men standing next to a small, dark-colored utility vehicle. The man on the left is wearing a grey jacket and a blue hard hat. The man on the right is wearing a blue hard hat, a blue jacket, and a high-visibility yellow safety vest. The vehicle has a sign on its side that reads '安全行车' (Safe Driving). A date stamp '2023/4/8' is visible in the bottom left corner of the photo.</p>

928	GX-B1417/22-Y-23044	2023年4月12日	综合判定：合格	
929	GX-B1417/22-Y-23045	2023年4月12日	综合判定：合格	

930	GX-B1417/22-Y-23046	2023年4月12日	综合判定：合格	 <p>A photograph showing a black SUV parked in front of a light blue building. Two workers, one in a grey uniform and red helmet, and another in a high-visibility vest and blue helmet, are standing next to the vehicle. The date '2023/4/8' is visible in the bottom right corner of the photo.</p>
931	GX-B1417/22-Y-23047	2023年4月12日	综合判定：合格	 <p>A photograph showing a white van parked in front of a building. Two workers, one in a grey uniform and red helmet, and another in a high-visibility vest and blue helmet, are standing in front of the van. The license plate is visible as '桂Y·K20R1'. The date '2023/4/8' is visible in the bottom left corner of the photo.</p>

932	GX-B1417/22-Y-23048	2023年4月12日	综合判定：合格	 A photograph showing two workers in safety gear standing in front of a white truck. The worker on the left is wearing a blue hard hat and a yellow safety vest over a grey shirt. The worker on the right is wearing a red hard hat and a grey jacket. The truck has a blue logo on its front. The background shows a multi-story building under a blue sky with some clouds. A yellow timestamp '2023/4/8' is visible in the bottom left corner of the photo.
933	GX-B1521/20-Y-23136	2023年4月12日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	 A photograph of a yellow hydraulic excavator at a construction site. The excavator is positioned on a pile of earth and rocks. A person is visible near the base of the machine. The background shows a clear blue sky and some distant hills. A yellow timestamp '2023/4/8' is visible in the bottom right corner of the photo.

934	GX-B1521/20-Y-23137	2023年4月12日	依据GB/T 9139-2018《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018《土方机械 液压挖掘机 试验方法》，所检项目合格。	 A yellow hydraulic excavator is shown in a construction site. The excavator is positioned in the center, with its arm raised. In the background, there are several yellow trucks and a building. A person is standing near the excavator. The sky is clear and blue. A yellow timestamp '2023/2/26' is visible in the bottom right corner of the image.
935	GX-B1521/20-Y-23138	2023年4月12日	依据GB/T 9139-2018《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018《土方机械 液压挖掘机 试验方法》，所检项目合格。	 A yellow hydraulic excavator is shown in a construction site. The excavator is positioned in the center, with its arm raised. In the background, there are hills and a clear sky. A person is standing near the excavator. A yellow timestamp '2023/2/26' is visible in the bottom right corner of the image.

936	GX-B1521/20-Y-23139	2023年4月12日	依据GB/T 9139-2018《土方机械 液压挖掘机 技术条件》GB/T 7586-2018《土方机械 液压挖掘机 试验方法》，所检项目合格。	
937	GX-B1521/20-Y-23140	2023年4月12日	依据GB/T 9139-2018《土方机械 液压挖掘机 技术条件》GB/T 7586-2018《土方机械 液压挖掘机 试验方法》，所检项目合格。	

938	GX-B1521/20-Y-23141	2023年4月12日	依据GB/T 9139-2018《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018《土方机械 液压挖掘机 试验方法》，所检项目合格。	
939	GX-B1521/20-Y-23142	2023年4月12日	依据GB/T 9139-2018《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018《土方机械 液压挖掘机 试验方法》，所检项目合格。	

940	GX-B1521/20-Y-23143	2023年4月12日	依据GB/T 9139-2018《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018《土方机械 液压挖掘机 试验方法》，所检项目合格。	
941	GX-B1521/20-Y-23144	2023年4月12日	依据GB/T 9139-2018《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018《土方机械 液压挖掘机 试验方法》，所检项目合格。	

942	GX-B1521/20-Y-23145	2023年4月12日	依据GB/T 9139-2018《土方机械 液压挖掘机 技术条件》GB/T 7586-2018《土方机械 液压挖掘机 试验方法》，所检项目合格。	
943	GX-B1417/22-Y-23039	2023年4月13日	综合判定：合格。	

944	GX-B1417/22-Y-23040	2023年4月13日	综合判定：合格。	
945	GX-B1417/22-Y-23041	2023年4月13日	综合判定：合格。	

946	GX-B1563/21-Y-23007	2023年4月14日	所检项目合格。	 <p>A photograph showing two workers in safety gear (hard hats and work clothes) standing next to a red truck with a silver tank. The tank has the Chinese characters '园林绿' (Garden Green) written on it. A yellow timestamp '2023/4/8' is visible in the bottom right corner of the image.</p>
947	GX-B1416/22-Y-23062	2023年4月14日	综合判定：合格。	 <p>A photograph showing a worker in an orange safety suit and helmet kneeling on the ground, working on a piece of machinery. The worker is using a tool. A yellow timestamp '2023/3/15' is visible in the bottom right corner of the image.</p>

948	GX-B1306/21-Y-23063	2023年4月13日	所检项目合格。	
949	GX-B1306/21-Y-23064	2023年4月13日	所检项目合格。	

950	GX-B1306/21-Y-23065	2023年4月13日	所检项目合格。	 A photograph showing a worker in a grey uniform and red hard hat inspecting a yellow piece of heavy machinery, possibly a generator or engine, in an outdoor setting. The worker is standing next to the machinery, which has a large yellow canopy. A yellow timestamp '2023/3/1' is visible in the bottom right corner of the image.
951	GX-B1306/21-Y-23066	2023年4月13日	所检项目合格。	 A photograph showing a worker in a grey uniform and red hard hat inspecting a blue piece of heavy machinery. The worker is standing next to the machinery, which has a large blue canopy. A white sign with the number 'H-3704' is visible on the side of the machinery. A yellow timestamp '2023/3/1' is visible in the bottom right corner of the image.

952	GX-B1306/21-Y-23067	2023年4月13日	所检项目合格。	
953	GX-B1306/21-Y-23068	2023年4月13日	所检项目合格。	

954	GX-B1306/21-Y-23069	2023年4月13日	所检项目合格。	
955	GX-B1417/22-Y-23018	2023年4月14日	综合判定：合格	

956	GX-B1417/22-Y-23019	2023年4月14日	综合判定：合格	
957	GX-B1417/22-Y-23020	2023年4月14日	综合判定：合格	

958	GX-B1417/22-Y-23021	2023年4月14日	综合判定：合格	
959	GX-B1417/22-Y-23022	2023年4月14日	综合判定：合格	

960	GX-B1417/22-Y-23023	2023年4月14日	综合判定：合格	
961	GX-B1417/22-Y-23024	2023年4月14日	综合判定：合格	

962	GX-B1417/22-Y-23025	2023年4月14日	综合判定：合格	
963	GX-B1417/22-Y-23026	2023年4月14日	综合判定：合格	

964	GX-B1417/22-Y-23027	2023年4月14日	综合判定：合格	
965	GX-B1417/22-Y-23028	2023年4月14日	综合判定：合格	

966	GX-B1417/22-Y-23029	2023年4月14日	综合判定：合格	 <p>A photograph showing two workers standing in front of a white truck. The worker on the left is wearing a red hard hat, a brown camouflage jacket, and dark pants. The worker on the right is wearing a grey hard hat, a blue jacket, and blue pants, and is wearing a white face mask. The truck has a blue license plate that reads "XY R2019". The background shows an outdoor industrial area with a building and a clear sky. A yellow timestamp "2023/3/5" is visible in the bottom right corner of the photo.</p>
967	GX-B1417/22-Y-23030	2023年4月14日	综合判定：合格	 <p>A photograph showing two workers standing in front of a white truck. The worker on the left is wearing a red hard hat, a brown camouflage jacket, and dark pants, and is wearing a white face mask. The worker on the right is wearing a black jacket and dark pants. The truck has a blue license plate that reads "XY C2501". The background shows an indoor or semi-enclosed industrial area. A yellow timestamp "2023/3/5" is visible in the bottom right corner of the photo.</p>

968	GX-B1417/22-Y-23031	2023年4月14日	综合判定：合格	
969	GX-B1417/22-Y-23032	2023年4月14日	综合判定：合格	