

序号	报告编号	发布日期	结论	影像资料
158	GX-B1423/20-1-23232	2023. 5. 19	综合判定：合格	
159	GX-B1423/20-1-23233	2023. 5. 19	综合判定：合格	

160	GX-B1423/20-1-23234	2023. 5. 19	综合判定：合格	
161	GX-B1423/20-1-23235	2023. 5. 19	综合判定：合格	

162	GX-B1423/20-1-23236	2023. 5. 19	综合判定：合格	 A yellow TONLY dump truck is parked on a dirt road. Two workers wearing hard hats and safety vests are standing in front of the truck. The truck has 'TONLY' written on its side.
163	GX-B1423/20-1-23237	2023. 5. 19	综合判定：合格	 A yellow dump truck is parked on a dirt road. Two workers wearing hard hats and safety vests are standing in front of the truck. The truck has Chinese characters on its side.

164	GX-B1423/20-1-23238	2023. 5. 19	综合判定：合格	
165	GX-B1423/20-1-23239	2023. 5. 19	综合判定：合格	

166	GX-B1423/20-1-23240	2023. 5. 19	综合判定：合格	
167	GX-B1382/21-1-23013	2023/5/19	综合判定合格	

168	GX-B1382/21-1-23014	2023/5/19	综合判定合格	
169	GX-B1451/20-1-23334~23335	2023. 5. 19	本次共检高压开关设备2台， 2台高压开关设备所检项目合格	

170	GX-B1310/21-1-23044	2023/5/19	符合标准要求	
171	GX-B1423/20-1-23222	2023. 5. 19	综合判定：合格	

172	GX-B1423/20-1-23223	2023. 5. 19	综合判定：合格	
173	GX-B1423/20-1-23224	2023. 5. 19	综合判定：合格	

174	GX-B1423/20-1-23225	2023. 5. 19	综合判定：合格	
175	GX-B1423/20-1-23226	2023. 5. 19	综合判定：合格	

176	GX-B1423/20-1-23227	2023. 5. 19	综合判定：合格	
177	GX-B1423/20-1-23228	2023. 5. 19	综合判定：合格	

178	GX-B1423/20-1-23229	2023. 5. 19	综合判定：合格	
179	GX-B1423/20-1-23230	2023. 5. 19	综合判定：合格	

180	GX-B1423/20-1-23231	2023. 5. 19	综合判定：合格	
181	GX-B1350/21-1-23017	2023. 5. 19	所检项目合格	

182	GX-B1500/21-1-23052	2023/5/22	综合判定：合格。	
183	GX-B1500/21-1-23053	2023/5/22	综合判定：合格。	

184	GX-B1500/21-1-23054	2023/5/22	综合判定：合格。	
185	GX-B1500/21-1-23055	2023/5/22	综合判定：合格。	

186	GX-B1500/21-1-23056	2023/5/22	综合判定：合格。	
187	GX-B1500/21-1-23057	2023/5/22	综合判定：合格。	

188	GX-B1500/21-1-23058	2023/5/22	综合判定：合格。	
189	GX-B1500/21-1-23059	2023/5/22	综合判定：合格。	

190	GX-B1500/21-1-23060	2023/5/22	综合判定：合格。	
191	GX-B1500/21-1-23061	2023/5/22	综合判定：合格。	

192	GX-B1500/21-1-23062	2023/5/22	综合判定：合格。	
193	GX-B1500/21-1-23063	2023/5/22	综合判定：合格。	

194	GX-B1500/21-1-23064	2023/5/22	综合判定：合格。	
195	GX-B1500/21-1-23065	2023/5/22	综合判定：合格。	

196	GX-B1500/21-1-23066	2023/5/22	综合判定：合格。	
197	GX-B1500/21-1-23067	2023/5/22	综合判定：合格。	

198	GX-B1500/21-1-23068	2023/5/22	综合判定：合格。	
199	GX-B1500/21-1-23069	2023/5/22	综合判定：合格。	

200	GX-B1500/21-1-23070	2023/5/22	综合判定：合格。	
201	GX-B1309/21-1-23013	2023/5/22	所检项目合格。	

202	GX-B1309/21-1-23014	2023/5/22	所检项目合格。	
203	GX-B1309/21-1-23015	2023/5/22	所检项目合格。	

204	GX-B1309/21-1-23016	2023/5/22	所检项目合格。	
205	GX-B1309/21-1-23017	2023/5/22	所检项目合格。	

206	GX-B1313/21-1-23054~23055	2023/5/22	本次共检电力变压器 2台，2台电力变压器所检项目合格。	
207	GX-B1328/20-1-23042	2023/5/22	所检项目合格。	

208	GX-B1328/20-1-23043	2023/5/22	所检项目合格。	 A photograph showing a person in a red shirt and blue pants standing on a ladder, inspecting the exterior of a building. The building has a white facade and a blue door. A yellow sign is visible on the wall. The date and time '2023/04/10' are printed in orange at the bottom right of the image.
209	GX-B1313/21-1-23056	2023/5/22	所检项目合格。	 A photograph showing a person in a red shirt and blue pants standing on a ladder, inspecting the exterior of a building. The building has a white facade and a blue door. A yellow sign is visible on the wall. The date and time '2023/04/10' are printed in yellow at the bottom left of the image.

210	GX-B1328/20-1-23044	2023/5/22	本次共检绝缘手套6只，6只绝缘手套所检项目合格。	
211	GX-B1328/20-1-23045	2023/5/22	本次共检绝缘鞋6只，6只绝缘鞋所检项目合格。	

212	GX-B1328/20-1-23046	2023/5/22	本次共检绝缘杆2组，2组绝缘杆所检项目合格。	
213	GX-B1328/20-1-23037	2023/5/22	本次共检绝缘手套110只，110只所检项目合格。	

214	GX-B1328/20-1-23038	2023/5/22	本次共检绝缘鞋140只，140只所检项目合格。	
215	GX-B1328/20-1-23039	2023/5/22	本次共检验电器40支，40支所检项目合格。	

216	GX-B1328/20-1-23040	2023/5/22	本次共检便携式短路接地线45套，45套所检项目合格。	
217	GX-B1328/20-1-23041	2023/5/22	本次共检绝缘杆10组，10组所检项目合格。	

218	GX-B1307/20-1-23055	2023/5/22	综合判定：合格。	
219	GX-B1307/20-1-23056	2023/5/22	综合判定：合格。	

220	GX-B1328/20-1-23049	2023/5/24	本次共检绝缘手套60只，60只所检项目合格。	
221	GX-B1328/20-1-23050	2023/5/24	本次共检绝缘鞋60只，60只所检项目合格。	

222	GX-B1423/20-1-23222	2023. 5. 25	综合判定：合格	
223	GX-B1423/20-1-23223	2023. 5. 25	综合判定：合格	

224	GX-B1423/20-1-23224	2023. 5. 25	综合判定：合格	
225	GX-B1423/20-1-23225	2023. 5. 25	综合判定：合格	

226	GX-B1423/20-1-23226	2023. 5. 25	综合判定：合格	
227	GX-B1423/20-1-23227	2023. 5. 25	综合判定：合格	

228	GX-B1423/20-1-23228	2023. 5. 25	综合判定：合格	
229	GX-B1423/20-1-23229	2023. 5. 25	综合判定：合格	

230	GX-B1423/20-1-23230	2023. 5. 25	综合判定：合格	
231	GX-B1423/20-1-23231	2023. 5. 25	综合判定：合格	

232	报告编号:GX-B1310/21-1-23045	2023. 5. 25	符合标准要求	
233	报告编号:GX-B1310/21-1-23046	2023. 5. 25	符合标准要求	

234	报告编号:GX-B1310/21-1-23047	2023. 5. 25	符合标准要求	
235	报告编号:GX-B1310/21-1-23048	2023. 5. 25	符合标准要求	

236	报告编号:GX-B1310/21-1-23049	2023. 5. 25	符合标准要求	
237	报告编号:GX-B1428/21-1-23045	2023. 5. 25	无缺陷迹痕显示	

238	报告编号:GX-B1428/21-1-23046	2023. 5. 25	无缺陷迹痕显示	
-----	--------------------------	-------------	---------	---