

序号	报告编号	发布日期	结论	影像资料
1	GX-B1522/20-Y-24115	2024年9月2日	所检项目合格。	
2	GX-B1328/20-Y-24067	2024年9月3日	本次共检验电器3支，3支 验电器所检项目合格。	

3	GX-B1339/21-Y-24011	2024年9月2日	所检项目合格。	
4	GX-B1339/21-Y-24012	2024年9月2日	所检项目合格。	

5	GX-B1521/20-Y-24568	2024年9月4日	所检项目合格。	
6	GX-B1521/20-Y-24569	2024年9月4日	所检项目合格。	

7	GX-B1521/20-Y-24570	2024年9月4日	所检项目合格。	 A close-up photograph of a person wearing a red hard hat and a light-colored short-sleeved shirt, sitting in the operator's cab of a Volvo excavator. The person is looking down at a control lever. A yellow date stamp '2024/8/24' is visible in the bottom left corner of the image.
8	GX-B1521/20-Y-24571	2024年9月4日	所检项目合格。	 A photograph of a Volvo excavator at a construction or mining site. The excavator is dark grey with yellow accents and is positioned next to a yellow dump truck. A person in a red hard hat is standing near the excavator. The background shows a large pile of grey material under a cloudy sky. A yellow date stamp '2024/8/24' is visible in the bottom right corner of the image.

9	GX-B1521/20-Y-24572	2024年9月4日	所检项目合格。	
10	GX-B1521/20-Y-24573	2024年9月4日	所检项目合格。	

11	GX-B1521/20-Y-24574	2024年9月4日	所检项目合格。	
12	GX-B1521/20-Y-24575	2024年9月4日	所检项目合格。	

13	GX-B1521/20-Y-24576	2024年9月4日	所检项目合格。	 A yellow Volvo excavator is shown in a construction or mining site, positioned on a dirt mound. Two workers wearing hard hats and safety vests are standing nearby. The sky is overcast. A yellow date stamp '2024/8/24' is visible in the bottom right corner of the image.
14	GX-B1521/20-Y-24577	2024年9月4日	所检项目合格。	 Two workers wearing red hard hats and high-visibility yellow vests are inside the cab of a Volvo excavator. One worker is seated at the controls, while the other stands next to the cab. A yellow date stamp '2024/8/24' is visible in the bottom left corner of the image.

15	GX-B1539/22-Y-24299	2024年9月4日	所检项目合格。	
16	GX-B1539/22-Y-24300	2024年9月4日	所检项目合格。	

17	GX-B1539/22-Y-24301	2024年9月4日	所检项目合格。	 A close-up photograph of a person wearing a red safety helmet and a white face mask, operating a vehicle. The person is seen from the side, looking forward. The background shows a bright sky and some structural elements of the vehicle. A yellow date stamp '2024/8/27' is visible in the bottom right corner.
18	GX-B1539/22-Y-24302	2024年9月4日	所检项目合格。	 A photograph of a yellow wheel loader parked on a dirt surface in a quarry or construction site. A worker in a white uniform and red helmet stands next to the front of the loader. The background shows a large pile of dark material and a clear blue sky. A yellow date stamp '2024/8/27' is visible in the bottom right corner.

19	GX-B1539/22-Y-24303	2024年9月4日	所检项目合格。	
20	GX-B1539/22-Y-24304	2024年9月4日	所检项目合格。	

21	GX-B1539/22-Y-24305	2024年9月4日	所检项目合格。	
22	GX-B1557/22-Y-24050	2024年9月4日	所检项目合格。	

23	GX-B1556/22-Y-24024	2024年9月4日	所检项目合格。	
24	GX-B1328/20-Y-24066	2024年9月4日	本次共检验电器11支，11支验电器所检项目合格。	

25	GX-B1415/22-Y-24014	2024年9月5日	综合判定：合格。	 A worker wearing a red helmet and dark clothing is operating a blue and orange machine in a dark tunnel. The machine has a control panel with a screen and buttons. The date 2024/8/28 is visible in the bottom right corner of the photo.
26	GX-B1415/22-Y-24015	2024年9月5日	综合判定：合格。	 A worker wearing a red helmet and dark clothing is standing in a dark tunnel, pointing upwards with their right hand. The tunnel walls are dark and rocky. The date 2024/8/28 is visible in the bottom right corner of the photo.